

## Initial Response Stage Report Island-wide Event

The information included in this report is current as of 1900 hours on 2025-04-16.

In compliance with Section 5.14(b) of the Transmission and Distribution Operation and Maintenance Agreement (T&D OMA) and the LUMA Emergency Response Plan (ERP), LUMA is providing the following Initial Response Stage Report:

LUMA Emergency Event Initial Response Stage Report	
1	<b>04/16/2025 at 1900 hours</b>
2	<b>Weather Forecast &amp; Monitoring</b> This event is not related to local weather conditions and the electric service recovery is not affected by current weather conditions.
3	<b>Event Summary</b> As 12:38 hours an island-wide blackout occurred.
4	<b>Safety</b> <ul style="list-style-type: none"> <li>No safety incidents have been reported.</li> </ul>
5	<b>Expected Event Classification Type and Changes to Event Classification Type</b> Preliminary classification is Type1 Event (Catastrophic), Level 4 (Partial Activation).
6	<b>Likelihood of LEOC Activation and Activation Level</b> LEOC was activated at 1500 hours on Wednesday, April 16, 2025. Activation Level 4 (Partial Activation) with expected level increase within the next 24 hours.
7	<b>System Operations</b> As of 1800 hours, the Status of Generation is the following: <ul style="list-style-type: none"> <li>Current Load: 18 MW</li> <li>Available Capacity: 30 MW</li> <li>Forecast Load: Not Applicable</li> <li>Total Reserve: Not Applicable</li> </ul> Power Plants Update: <ul style="list-style-type: none"> <li>Palo Seco 1-1 Unit and Palo Seco 1-2 Unit are online with 8MW and 18MW, respectively.</li> <li>Palo Seco Mobile Pack-1 is online with 10MW.</li> </ul> As of 1800 hours, the Status of Transmission System is the following: <ul style="list-style-type: none"> <li>Palo Seco to Monacillo lines were energized to begin restoration of critical facilities.</li> </ul> As of 1800 hours, the Status of Distribution System is the following: <ul style="list-style-type: none"> <li>Distribution feeders in service:               <ul style="list-style-type: none"> <li>1806-1, 2, 3 Levittown Substation</li> <li>1303-1, 2, 4, 5 – Villa Betina</li> <li>3801-1, 2 - Culebra</li> </ul> </li> <li>Culebra generators are in service with 1.4MW.</li> </ul>
8	<b>LUMA Resource Readiness</b> <ul style="list-style-type: none"> <li>134 FTE field workers</li> </ul>

## Initial Response Stage Report Island-wide Event

LUMA Emergency Event Initial Response Stage Report	
9	<b>Forecasted Number and Type of Total Resources Required</b> Pending until preliminary damage assessments are completed.
10	<b>Number of External Resources Secured</b> <ul style="list-style-type: none"> <li>On standby</li> </ul>
11	<b>Initial Response Stage Status</b> Initial Response
12	<b>Global and Regional ETRs (If available)</b> It is projected that 90% of customers will see power restored within the next 48 to 72 hours.
13	<b>Restoration Stage Status</b> Initial Response
14	<b>Customer Outages</b> Explained on the following points 15 and 16.
15	<b>Total Customers with Service</b> 20,462(1.4%)
16	<b>Total Customers without Service</b> 1,447,761 (9.8.6%)
17	<b>Status of Life Preserving Equipment Dependent (Customers) and Critical Customers</b>
18	<b>Problems Anticipated / Encountered for Event</b> Pending until damage assessments are complete.
19	<b>Any Other Pertinent Information:</b> <ul style="list-style-type: none"> <li>As of 1800, LUMA has issued 2 media statements, 2 social media updates, and has held a press conference.</li> <li>PREMB activated Central COE at 1800 hours and LUMA's Interagency Coordinator is on site.</li> <li>We have been able to establish communication with all 78 municipalities.</li> <li>As of 1800, the Call Center waiting time was 3 minutes 49 seconds with 0 calls in the queue.</li> <li>LUMA have been able to establish communication with all 78 municipalities.</li> </ul>